



HE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Ji Sick HWANG, et al.

Application No.: 10/790,701

Confirmation No.: 4309

Filed: March 3, 2004

U.S. Patent No.: 6,945,057

Issued: September 20, 2005

For: ICE MAKER ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Batch No.:

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Certificate MAY 2 3 2006

of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

By:

Gene M. Garner, II Registration No. 34,172

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,945,057

DATED: September 20, 2005

INVENTOR(S): Ji Sick HWANG, et al.

On the cover page, (75) Inventors, change "Kwangiu" to --Kwangju-- for the first, second, third and fourth inventors.

On the cover page, (56) References Cited, U.S. Patent Documents, column 2, line 4, change "Mateck" to --Maleck--

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 6,945,057

No. of add'l copies @ 50¢ per page

